

Motor Adapter VK



Dimension ØO is also used for tapped holes. In case of tapped holes, prefix M must be applied.



- 1 MGBS/MGTB
- 2 Motor adapter housing
- 3 Motor adapter flange
- Motor adapter VK

4 - Motor